

Classic Bearing Damage Modes

Ryan D. Evans, Ph.D.
Manager – Bearing Fundamentals & Tribology
The Timken Company

Wind Turbine Tribology Seminar
NREL-Argonne-DoE
Broomfield, CO, USA
November 2011

TIMKEN
Where You Turn

Goals

- **Introduce to classic bearing damage modes**
 - Recognize types of bearing damage
 - Offer possible causes for bearing damage
 - Suggestions for the prevention of damage
- **“White Etch Areas” damage mode**
 - Terminology
 - Background on microstructural alterations
 - Recent transmission electron microscopy (TEM) investigations

How is bearing life defined?

- A rolling mill roll neck bearing may have extended service life even with signs of damage if properly repaired.
- High speed dental hand piece bearing life determined by bit speed at a given driving pneumatic pressure.
- Wheel end bearing for mining truck may be limited by peeling and spalling damage.
- Medical equipment bearing life limited by noise and vibration characteristics.
- Wind turbine main shaft bearing limited by occurrence of spalls.

**Divide damage modes into two categories:
Material Fatigue & Wear**

Bearing Damage Modes:

Material Fatigue

- **L_{10} fatigue life** – the number of hours (or cycles) that 90% of a group of (apparently identical) bearings will meet or exceed, under a given set of conditions, before specified fatigue damage occurs.
- **Life models predict statistical likelihood that material defects in cyclic stressed volume will create spalls.**
 - Factor-based analysis (catalog with adjustment factors)
 - Stress-based analysis
- **Adjustment factors on predicted life account for:**
 - Reliability
 - Material
 - Environmental conditions (lubrication, misalignment, debris...)

Material Fatigue: Spalling




Material Fatigue: Inclusion Origin Spalling



INCLUSION




Material Fatigue: Point Surface Origin (PSO) Spalling



**Spalling from debris or raised metal exceeding
lubricant film thickness on a tapered roller bearing**

Material Fatigue: Geometric Stress Conc. (GSC) Spalling



Spalling from misalignment, deflections or heavy loading on a tapered roller bearing

Bearing Damage Modes: Wear or Other Damage

- **Potential causes of wear or other damage are numerous:**
 - **Faulty mounting**
 - **Improper adjustment**
 - **Lack of lubrication**
 - **Contamination**
 - **Improper handling, storage, or transport**
 - **Improper maintenance**
 - **Exceeding machine limits**
 - **Environmental factors (temperature, atmosphere, etc.)**
- **Divide damage causes into (3) general categories:**
 - **Contamination**
 - **Inadequate Lubrication**
 - **Misuse**

Contamination: Abrasive Wear




Tapered roller bearing abrasive wear




**Spherical roller bearing fine
particle contamination**

Contamination: Bruising



**Cylindrical roller bearing
outer ring bruising**



**Contamination bruising from
hard particles in spherical
roller bearing**

Contamination: Denting


Ball



Spherical roller




Tapered roller




Debris denting

Contamination: Soft vs. Hard Ductile Particles



Hard Ductile Particle



Soft Ductile Particle

Contamination: Prevention of Particulate Damage

- Regular inspection of seals
- Ensure clean lubricant supply
- Use proper bearing removal, cleaning and replacement procedures
- Don't remove bearing from package until ready for mounting
- Ensure clean shop and tools
- Protect from dirt
- Regular maintenance or replacement of filtration elements. Do not bypass the filter.

Contamination: Etching / Corrosion



**Etching and corrosion on
cylindrical roller bearing inner ring**



**Advanced corrosion and
pitting on the cone race and
rollers**

Contamination: Etching / Corrosion



Heavy water damage on a ball bearing inner ring and cage



A tapered roller bearing cup with corrosion on the race

Contamination: Etching / Corrosion Prevention

- Inspect and replace worn seals to avoid etching due to exposure to moisture
- Monitor moisture level in lubricant
- Ensure that bearings are stored in a dry area
 - Before storage, bearings should receive a coating of oil or other rust preventative
 - Wrap bearings in protective paper or covering
- After washing / cleaning, bearings should be thoroughly dried


Contamination: Fretting Corrosion



Inadequate Lubrication

- Any condition that allows metal-to-metal contact in a bearing can be regarded as “inadequate lubrication”
- Sources / Causes:
 - Lubricant starvation
 - Insufficient lubricant to sustain a film
 - Wrong kind of lubricant for the speed and load
 - Wrong grade of lubricant
 - Wrong type of lubricant system, such as the use of an oil level and splash system when operating conditions require a circulating system

Inadequate Lubrication: Peeling



**Microspalling (peeling) due to
thin film from high load/low
RPM or high temperatures**

Inadequate Lubrication: Rib – Roller End Scoring





**Heat damage on tapered rollers
from metal-to-metal contact**



**Scoring of tapered roller ends
and rib face**


Inadequate Lubrication: Heat Discoloration



Inadequate Lubrication: Smearing




- Thrust SRB Roller with Smearing Damage



Smear bands

Inadequate Lubrication: Smearing


- **Smeared TRB
Cone Raceway**



Smearing

Goal – Produce smearing in full-scale CRB, and evaluate effectiveness of surface treatment options to mitigate it.

Full-Scale CRB Smearing Test Program: Test Equipment and Materials



Timken 4-S Test Rig

Rig Characteristic	Range or Description
Speed (rpm)	0 to 3600
Radial Load (kN)	0 to 44.5
Thrust Load (kN)	0 to 22.3
Temperature Sensing	Thermocouples for oil and test bearings
Spindle Torque	Inline torque meter
Cage Speed	Proximity sensor/tachometer
Vibration	Accelerometer

Full-Scale CRB Smearing Test Program: Test Equipment and Materials

- **T-6411-A cylindrical roller bearing**
 - NU-type.
 - OD = 290 mm, Bore = 160 mm, Width = 98.425 mm
- **(4) test treatments, (3) bearings tested per treatment**



Treatment ID	Treatment Description
Ground	Standard Ground Rings and Rollers
Honed / ES20	Honed Raceways, ES20 Roller Texturing
Honed / ES20 / Black Oxide	Honed Raceways, ES20 Roller Texturing, Black Oxide Treatment on both Rings and Rollers
Wear-Resistant	Honed Raceways, ES322 Texture and Coating on Rollers

Full-Scale CRB Smearing Test Program:

Test Protocol

- It was not easy to achieve smearing!
- Attempted conditions include:
 - Steady state load and speed conditions for short and long test durations
 - Monotonic load level step-down at constant speed
 - Oscillating load level between a constant “high” level and successively lower step levels at constant speed
 - Oscillating load level between a constant “low” level and successively higher step levels at constant speed
 - Stepping the load level above and below a constant “medium” level at constant speed
 - Fixing various constant load levels and dropping the speed to a low level and then rapidly accelerating to a higher level
 - Various oil type, temperature, and starvation conditions
 - etc...



Full-Scale CRB Smearing Test Program: Test Protocol

- A constant speed test with a two-stage radial load profile worked.
 - 1st load stage: square wave, alternating load direction between 12 & 6 o'clock.
 - 2nd load stage: nominal “zero” load condition (small load to offset shaft weight).

Test Parameter	Value
Load (kN) (as a function of time in min)	$P(t) = \begin{cases} 17.8(-1)^{\lfloor 4t \rfloor}, & \text{if } 0 \leq t \leq 40 \\ 0.7, & \text{if } 40 < t \leq 100 \end{cases}$
Speed (rpm)	1800
Oil Flow Rate (mL/min)	47.3
Oil Inlet Temp	Not Controlled – Lab Temp
Oil Type	SAE 20, Polyalphaolefin Synthetic with no EP/AW Additives
Total Test Duration (min)	100


* 17.8 kN is ~1.5% C1 rating for bearing

Full-Scale CRB Smearing Test Program: Test Results



- Smearing achieved by creating high roller-raceway sliding conditions via load direction reversal.
- First (3) mins of a representative test shown at left:
 - Significant drop in cage speed during load disengagement and subsequent cage/roller acceleration on reengagement.
 - Accompanying torque instability during load direction change.

Full-Scale CRB Smearing Test Program: Test Results





Each bar represents (3) replicate tests from which no variation in result from test to test was observed. That is, all WRB tests were suspended after 3 test cycles with no smearing. All standard tests smeared after 1 test cycle, etc.



Full-Scale CRB Smearing Test Program: Post-Test Bearing Analysis



Full-Scale CRB Smearing Test Program: Post-Test Bearing Analysis





Honed/ES20



Honed/ES20/Black Oxide



Adhesive Wear Damage

Full-Scale CRB Smearing Test Program: Post-Test Bearing Analysis



Mild Plastic
Deformation

Ground




Wear-Resistant

Full-Scale CRB Smearing Test Program: Post-Test Bearing Analysis

- **Smearing damage was achieved in full-scale CRB using a two-part test with a period of repetitive load direction reversals (load ~1.5% of the C1 dynamic load rating) followed by steady operation at a nominal zero-load condition.**
- **Wear-Resistant bearings featuring special roller coatings were the only treatment that prevented smearing in these tests.**
- **Black oxide treatment did not provide additional smearing protection over the Honed/ES20 case that had similar raceway and roller body roughness in these tests.**
- **Surface finish and roughness specifications must be carefully considered in applications that are susceptible to smearing.**

Inadequate Lubrication: False Brinelling




Inadequate Lubrication: Prevention

- Ensure that an appropriate amount of the correct type and grade of lubricant is present
- In environments where lubricant may be washed out, select a sealed bearing
- Ensure that the correct lubricant delivery system is used
- Proper grease pack/distribution
- Ensure flow starts before rotation or operation
- Ensure proper function of lube system: proper flow rates, proper settings and maintenance of metering devices
- Ensure proper temperature in oil sump or inlet

Misuse: Excessive Preload or Overload



Overloading on a cylindrical roller bearing caused roller surfaces to fracture




Overloading resulted in severe fatigue spalling on the tapered rollers

Misuse: Excessive Preload or Overload



**Overloading and low speed
caused insufficient lubricant film**

Misuse: True Brinelling



**Spherical roller bearing inner ring showing
roller impact damage from shock loading**

Misuse: True Brinelling




Needle roller bearing outer ring race with roller-spaced indents from impact during installation


Misuse:

True vs. False Brinelling

- False brinelling wears away the surface texture, while the original surface texture remains in the depression of a true brinell




True Brinelling




False Brinelling

Misuse: Burns from Electric Current



**Pitting / small burns created by arcs from
improper electric grounding in stationary bearing**

Misuse: Burns from Electric Current



Fluting (small axial burns) caused by electric current passing through rotating bearing

Misuse: Burns from Electric Current



**Roller with fluting caused by welding performed
on machine while bearings were rotating**

Keys To Optimal Bearing Performance

Proper:

- **Selection/Specification**
- **Handling**
- **Installation**
- **Lubrication**
- **Sealing**
- **Cleaning**

Minimize Contamination, Inadequate Lubrication, and Misuse!


What are White Etch Areas?

- **Microstructural Alterations:** Phase transformations that occur during service due to high application stresses and/or long service lives.
- The location of nucleation sites for these phase transformations can be found to be either:
 - Random (within a depth interval consistent with high applied stresses – e.g., 0.005”-0.023”)
 - Dark etch regions
 - White etch areas
 - Specific (at lower strength areas or stress risers within the original microstructure or steel)
 - White bands
 - Butterfly

Microstructural Alterations - Terminology

- **Dark Etching Areas**
 - Dark Tint
 - Dark Line
 - Dark Etching Regions (DER)
 - Dark Needles
 - Dark Etching Bands
- **White Bands**
 - 80 or 30 Degree Bands
 - White Etch Areas (WEA)
 - White Etching Alterations (WEA)
 - Light Etching Areas
 - Light Etching Region
 - Bright Etching Regions (BER)
 - High/Low Angle Bands
 - Steep/Flat White Band
- **Butterfly**
 - Stress Butterfly
 - White Etch Areas
- **White Etch Cracking**
 - White Etch Areas (WEA)
 - Brittle Flaking
 - White Structure Flaking
 - White Band
 - Bright Etched Regions
 - irWEA
 - irregular white etch areas
 - Inner ring white etch areas
- **Axial Cracking**
 - Radial Cracking


Dark Etching Areas & White Bands



- Accumulation of subsurface damage with increasing cycles.


Source: Schwan et al., Metallurgical Transactions A, vol 76, August 1976, page 1100

Dark Etching Areas – Hardness Changes



Source: Schwan et al., Metallurgical Transactions A, vol 76, August 1976, page 1101

Butterfly – Morphology & Orientation




Butterfly – Micro Hardness

- SAE 52100
 - Knoop Hardness
 - Used 25 gram load
 - 3% Nital Etch
 - Originally 800X
 - Nomarski Polarized Lighting
-
- Matrix = 825 KHN = HRC 64
 - Butterfly = 1780 KHN
 >> HRC 70


Source: Torrington Met Lab Archive




White Etch Cracking



White Etch Areas - TEM



White Etch Areas - TEM



White Etch Area Take-Aways

- Investigations are underway to better understand WEA network microstructural alterations and their causes.
- Current understanding is that WEA are linked to brittle flaking and possibly axial cracking as well.
- Literature and analogies between WEA networks and stress butterflies/DER-WBs point toward a mechanical root cause, likely involving high stress and slip conditions.



Summary

- It is usually easy to see bearing damage, but often difficult to determine the cause.
- In many cases the bearing damage may be due to a combination of causes.
- Requires complete investigation of mounting, installation and related parts.
- Smearing was achieved with full-scale CRB in the lab by oscillating the load zone direction, and only Wear-Resistant bearings were able to survive without smearing under those conditions.
- A study of WEA microstructural alterations is underway.

Acknowledgments

- The Timken Company for permission to present.
- S. Hyde, T. Barr, L. Houpert, D. Lucas, S. Boyd, and D. Pierman from Timken.
- G. Doll, P. Shiller from the Timken Engineered Surfaces Laboratory at the Univ. of Akron.

Questions?

TIMKEN

Where You Turn